UNCLASSIFIED

AD NUMBER AD907291 LIMITATION CHANGES TO: Approved for public release; distribution is unlimited. FROM: Distribution authorized to U.S. Gov't. agencies only; Test and Evaluation; DEC 1972. Other requests shall be referred to Army Aviation Systems Command, Attn: AMSAV-EF, Post Office Box 209, St. Lonis, MO 63166. **AUTHORITY** USAAVSCOM ltr, 12 Nov 1973



AD RDTE PROJECT NO.
AVSCOM PROJECT NO. 71-24
USAASTA PROJECT NO. 71-24

EVALUATION OF THE OH-58A HELICOPTER WITH AN ALLISON 250-C20 ENGINE

FINAL REPORT

EMMETT J. LAING PROJECT OFFICER/ENGINEER

TOM P. BENSON PROJECT ENGINEER

ALTON W. WERNER SP5 US ARMY PROJECT ENGINEER DONALD G. BROADHURST MAJ, CE US ARMY PROJECT PILOT

PARMINI


FEB 12 1973

DECEMBER 1972

Distribution limited to United States Government agencies only; test and evaluation, December 1972. Other requests for this document must be referred to the Commander, United States Army Aviation Systems Command, Attention: AMSAV-EF, Post Office Box 209, St. Louis, Missouri 63166.

UNITED STATES ARMY AVIATION SYSTEMS TEST ACTIVITY EDWARDS AIR FORCE BASE, CALIFORNIA 93523

DISCLAIMER NOTICE



THIS DOCUMENT IS BEST QUALITY AVAILABLE. THE COPY FURNISHED TO DTIC CONTAINED A SIGNIFICANT NUMBER OF PAGES WHICH DO NOT REPRODUCE LEGIBLY.

DISCLAIMER NOTICE

The findings of this report are not to be construed as an official Department of the Army position unless so designated by other authorized documents.

REPRODUCTION LIMITATIONS

Reproduction of this document in whole or in part is prohibited except with permission obtained through the Commander, United States Army Aviation Systems Command, Attention: AMSAV-EF, Post Office Box 209, St. Lonis, Missonri 63166. The Defense Documentation Center, Cameron Station, Alexandria, Virginia 22314, is authorized to reproduce the document for United States Government purposes.

DISPOSITION INSTRUCTIONS

Destroy this report when it is no longer needed. Do not return it to the originator.

TRADE NAMES

The use of trade names in this report does not constitute an official endorsement or approval of the use of the commercial hardware and software,

RDTE PROJECT NO. AVSCOM PROJECT NO. 71-24 USAASTA PROJECT NO. 71-24

EVALUATION OF THE OH-58A HELICOPTER WITH AN ALLISON 250-C20 ENGINE

FINAL REPORT

EMMETT J. LAING PROJECT OFFICER/ENGINEER

TOM P. BENSON PROJECT ENGINEER

ALTON W. WERNER SP5 US ARMY PROJECT ENGINEER DONALD G. BROADHURST MAJ, CE US ARMY PROJECT PILOT

DECEMBER 1972

Distribution limited to United States Government agencies <u>only</u>; test and evaluation, December 1972. Other requests for this document must be referred to the Commander, United States Army Aviation Systems Command, Attention: AMSAV-EF, Post Office Box 209, St. Louis, Missouri 63166.

UNITED STATES ARMY AVIATION SYSTEMS TEST ACTIVITY EDWARDS AIR FORCE BASE, CALIFORNIA 93523

FOREWORD

Technical assistance was provided by the engine manufacturer, Detroit Diesel Allison Division of General Motors.

ABSTRACT

The United States Army Aviation Systems Test Activity conducted a limited performance and handling qualities evaluation of the Bell Helicopter Company model OH-58A helicopter with an Allison 250-C20 engine installed. The evaluation was conducted at Edwards Air Force Base, and Bishop, California, during the period 22 September 1971 to 7 January 1972. Twenty-five flights, 21.2 productive test hours, were required for the evaluation. Test results obtained with the Allison 250-C20 engine were compared with those previously obtained with the standard T63-A-700 engine. The primary performance improvement noted was an increase in out-of-ground-effect hover ceiling at a 3000-pound gross weight to 10,000 feet from 4600 feet. The long-range cruise airspeed was increased to 111 knots true airspeed from 104 knots true airspeed at a 5000-foot density altitude and a 3000-pound gross weight. The increased engine power did not significantly increase the service ceiling over the basic OH-58A at identical gross weights. One shortcoming, insufficient left directional control at 35 knots true airspeed in right sideward flight, was noted. Within the scope of the test, the performance of the OH-58A helicopter with the Allison 250-C20 engine was improved over the basic OH-58A helicopter. Handling qualities were essentially unchanged.

TABLE OF CONTENTS

	Page
INTRODUCTION	
Background	1
Test Objectives	
Description	1
Scope of Test	1
Methods of Test	_
Chronology	3
RESULTS AND DISCUSSION	
General	4
Performance	4
General	4
Hover Performance	
Level Flight Performance	5
Climb Performance	5
Handling Qualities	7
General	7
Sideward Flight Characteristics	7
Control Positions in Trimmed Forward Flight	7
Collective-Fixed Static Longitudinal Stability	8
Autorotational Characteristics	8
Miscellaneous Tests	10
Engine Characteristics	4.0
Engine Governing Characteristics	10
CONCLUSIONS	
General	12
Shortcoming Affecting Mission Accomplishment	
Specification Compliance	
RECOMMENDATIONS	13

																		Page
APP	ENDIXES																	
	References																	
	Safety-of-Flight Release Test Instrumentation .																	
D.	Test Data	٠	٠	٠	٠	٠	٠	٠	٠	٠	٠	•	٠	٠	٠	٠	٠	23

DISTRIBUTION

INTRODUCTION

BACKGROUND

t. The 250-C20 gas turbine engine is a growth version of the T63-A-700 engine manufactured by the Detroit Diesel Allison Division of General Motors Corporation. Engineering flight tests of the Bell Helicopter Company model OH-58A helicopter with the T63-A-700 engine were previously conducted by the United States Army Aviation Systems Test Activity (USAASTA) (refs 1 and 2, app A). The United States Army Aviation Systems Command (AVSCOM) directed USAASTA to conduct an evaluation of the OH-58A helicopter with the 250-C20 engine installed (refs 3 and 4).

TEST OBJECTIVE

2. The objective of this test was to evaluate the performance and handling qualities of the OH-58A helicopter with an Allison 250-C20 engine installed.

DESCRIPTION

3. The OH-58A is a single-main-rotor, turbine-powered, light observation helicopter, manufactured by Bell Helicopter Company, Fort Worth, Texas. The main rotor is a two-bladed, semirigid, teetering type; and the tail rotor is a two-bladed, semirigid, delta-three hinge type. The cockpit configuration is two place (pilot and copilot/observer), and the cargo compartment has provisions for seating two passengers. Dual flight controls are provided with cyclic and collective controls boosted, and the tail rotor controls unboosted. The main landing gear is a fixed, energy-absorbing, skid type. For this testing, the helicopter was powered by an Altison 250-C20 free gas turbine engine with a military rated power of 400 shaft horsepower (slip) derated to the transmission power limit of 270 slip (maximum continuous) with a takeoff power limit of 317 slip (5 minutes). A detailed description of the OH-58A helicopter is contained in the operator's manual (ref. 5, app. A).

SCOPE OF TEST

4. Flight testing of the OH-58A helicopter with the 250-C20 engine installed was conducted at Edwards Air Force Base, and Bishop, California, during the period 22 September 1971 through 7 January 1972 by USAASTA personnel. Twenty-five test flights consisting of 21.2 productive hours were conducted under the conditions listed in table 1.

Table 1. Test Conditions. 1

Test	Calibrated Airspeed (kt)	Gross Weight (1b)	Density Altitude (ft)	Average Outside Air Temperature (°C)	Average Center of Gravity (in.)
Hover performance ²	Zero	2463 to 3209	10,300 to 11,700	5	108.0 (fwd)
Level flight performance	20 to 93	3150 to 3200	8,350 to 14,170	-6.74 to -1.34	107.1 (£wd)
Climb performance	38 to 50	3213 (takeoff)	1,200 to 16,800	NA	107.0 (£wd)
Sideward flight	Zero to ³35	2460 to 2785	9,920 to 11,340	1.9 to 13.6	109.0 (mid)
Trim control positions	32 to 103	3115 to 3200	7,750 to 14,420	-6.7 to 2.0	107.1 (fwd) 111.4 (aft)
Static longitudinal stability	61, 80, 102	3115	7,750	2.0	111.4 (aft)
Autorotational entry characteristics	Zero to 117	2570 to 3215	6,000	19	106.8 (fwd)
Engine governing characteristics	80	3140	7,000	12	107.0 (fwd)

Rotor speed: 354 rpm.

Out of ground effect (50-foot skid height).
In ground effect (4-foot skid height).

Rhots true airspeed.

5. Test results were compared to those previously reported for the OH-58A helicopter with the T63-A-700 engine (refs 1 and 2, app A). Flight limitations contained in the operator's manual (ref 5) and the safety-of-flight release (app B) were observed during the test.

METHODS OF TEST

6. Flight test methods used are briefly described in the Results and Discussion section of this report. Performance data were manually recorded from coekpit instrumentation. All performance data are based on specification engine performance (ref 6, app A) adjusted for T63-A-700 installation losses (ref 1). Flying qualities data were recorded by an oscillograph located in the eargo/passenger compartment. A detailed list of test instrumentation is contained in appendix C.

CHRONOLOGY

7. The chronology of the OH-58A helicopter with Allison 250-C20 engine evaluation is as follows:

Test directive received	24	June	1971
Allison 250-C20 engine installed	16	September	1971
Flight tests started	22	September	1971
Flight tests completed	7	January	1972

RESULTS AND DISCUSSION

GENERAL

A limited performance and handling qualities evaluation of the OH-58A helicopter with an Allison 250-C20 engine installed was conducted by the United States Army Aviation Systems Test Activity personnel. Performance testing included hover, level flight, and climb performance. Handling qualities were evaluated during sideward flight, forward flight, and autorotational entries. Primary performance improvement over the standard T63-A-700 engine was an increase in out-of-ground-effect hover ceiling to 10,000 feet from 4600 feet. The specific range was essentially unchanged, but there was an increase of the long-range cruise airspeed to 111 knots true airspeed from 104 knots true airspeed at a 5000-foot density altitude and a 3000-pound gross weight. The climb capability of the aircraft was not limited by engine power available. Instead, an apparent maximum rotor thrust limit which occurred at a 6800-foot density altitude, a 3150-pound gross weight, and a thrust coefficient of 0.00531 prevented climbing to higher altitudes. One shortcoming, insufficient left directional control at 35 knots true airspeed in right sideward flight, was noted. Within the scope of the test, the performance of the OH-58A helicopter with the Allison 250-C20 engine was improved over the basic OH-58A helicopter, while handling qualities were essentially unchanged.

PERFORMANCE

9. Performance testing of the OH-58A helicopter with the Allison 250-C20 engine was conducted at a hover, in level flight, and in climbs. Performance test results were compared to results obtained with the previously tested T63-A-700 engine. The out-of-ground-effect (OGE) hover ceiling was increased to 10,000 feet from 4600 feet. The specific range was essentially unchanged, but there was an increase of the long-range cruise airspeed to 111 KTAS from 104 KTAS at a 5000-foot density altitude and a 3000-pound gross weight. A service ceiling of 16,800 feet at a 3200-pound gross weight was obtained during climb testing. Within the scope of the test, the performance characteristics of the OH-58A helicopter with the Allison 250-C20 engine are improved over the basic OH-58A helicopter.

Hover Performance

10. Hover performance tests were conducted at skid heights of 4 feet in ground effect (IGE), and 50 feet OGE under the conditions shown in table 1. The free-flight hover method was used to determine hover performance. Skid height was measured by visual reference to a measured weighted cord attached to the right skid. Incremental amounts of ballast were added to the helicopter until either the engine temperature or transmission power limit was reached. Test results are presented in figures 1 and 2, appendix D.


11. A comparison of the standard-day hover performance with the 250-C20 and T63-A-700 engine is presented as figure A. The OH-58A with the 250-C20 engine installed had an increase in OGE hover ceiling to 10,000 feet from 4600 feet at a gross weight of 3000 pounds. The increased hover performance of the OH-58A with the 250-C20 engine enhances its operational capability. Within the scope of the test, the hover performance of the OH-58A helicopter with the 250-C20 engine is improved over the basic OH-58A helicopter.

Level Flight Performance

12. Level flight performance tests were conducted to determine power required and associated fuel flow as a function of airspeed. In addition, specific range, long-range cruise airspeed, and maximum airspeed in level flight were determined. Test conditions are presented in table 1. Data were obtained in stabilized coordinated level flight using the referred gross weight method of test. Test results are presented in figures 3 through 6, appendix D. Level flight range summaries are presented as figures 7 through 9. For altitudes at sea level, 5000, and 10,000 feet, long-range cruise airspeed increased for the 250-C20 engine. There was essentially no change in the specific range. Within the scope of this test, the level flight performance of the OH-58A helicopter with the 250-C20 engine is improved over the basic OH-58A helicopter.

Climb Performance

- 13. Continuous climbs were conducted from a 1200-foot density altitude to the service ceiling under the conditions listed in table 1. The climb airspeeds used were determined from previous climb tests (ref. 1, app. A). Test results are presented in figure 10, appendix D.
- 14. An abrupt reduction in the rate of climb accompanied by intense airframe vibrations was noted above a density altitude of 16,000 feet. Attempts to increase the rate of climb at the service ceiling of 16,800 feet by varying airspeed from the scheduled 34 knots indicated airspeed (KIAS) had no effect except that vibrations increased markedly at higher airspeed followed by immediate altitude losses. At slower airspeeds the vibrations decreased, but again the helicopter lost altitude. The sharp decrease in rate of climb and the vibrations encountered are attributed to an apparent rotor thrust limit which occurred at a 16,800-foot density altitude, a 3150-pound gross weight, and a CT of 0.00531. Despite an increase in power available with the 250-C20 engine, the service ceiling is not significantly increased over the basic OH-58A at identical gross weights.



HANDLING QUALITIES

General

15. A limited handling qualities evaluation of the OH-58A helicopter with the Allison 250-C20 engine was conducted under day visual-flight-rules conditions. Sideward flight, forward flight, and autorotational entries were conducted, and the results were compared to those obtained with the standard T63-A-700 engine. One shortcoming, insufficient left pedal at 35 knots true airspeed in right sideward flight, was noted. Within the scope of this test, the handling qualities of the OH-58A helicopter with the Allison 250-C20 engine were essentially unchanged from the basic OH-58A helicopter.

Sideward Flight Characteristics

- 16. Sideward flight characteristics were evaluated at the conditions shown in table 1. Wind azimuths at 45, 90, and 135 degrees relative to the nose of the helicopter were used. These azimuths were considered critical due to previous data contained in reference 2, appendix A. Test results are presented in figure 11, appendix D.
- 17. Previous right sideward flight test at a CT of 0.00343 resulted in a left pedal margin of 5 percent at 35 KTAS (ref 2, app A). Results of tests with the 250-C20 engine showed that at 35 KTAS, the directional control margin rapidly diminished with increased CT's. In 35-KTAS right sideward flight at a CT of 0.00392, the directional control margin was reduced to less than 2 percent. Although aircraft control could be maintained, there was not sufficient left directional control to counteract a lateral gust disturbance. However, at 30 KTAS, at least a 12-percent directional control margin remained. Directional control in 35-KTAS right sideward flight failed to meet the requirements of paragraph 3.3.4 of M1L-11-8501A. Insufficient left directional control in 35-KTAS right sideward flight is a shortcoming.

Control Positions in Trimmed Forward Flight

- 18. Control positions in trimmed forward flight were evaluated from 32 to 103 knots calibrated airspeed under the conditions shown in table 1. Test results are presented in figures 12 and 13, appendix D. for all test conditions, increasing forward longitudinal control movement was required for increased trim speed. The variation in longitudinal control position between autorotations and maximum-power climbs was approximately 1.2 inches.
- 19. Directional and lateral control positions varied less than I inch for a given configuration throughout the airspeed range tested. No significant variation in directional or lateral control positions was noted when transitioning from a maximum-power climb to an autorotation. The requirements of paragraphs 3.2.10.2 and 3.3.17 of MIL-H-8501A (ref. 7, app. A) were met. Within the scope of the

test, the control position characteristics of the OH-58A helicopter with the 250-C20 engine are essentially unchanged from the basic OH-58A helicopter.

Collective-Fixed Static Lougitudinal Stability

- 20. Collective-fixed static longitudinal stability was evaluated under the conditions listed in table 1. The tests were conducted by initially trimming the helicopter at the desired airspeed and then stabilizing at slower and faster airspeeds while holding constant collective pitch. Test results are presented in figure 14, appendix D.
- 21. For the configurations tested, the aircraft possessed static longitudinal stability as evidenced by forward longitudinal control displacement for increased airspeed, and aft longitudinal control displacement for decreased airspeed from trim. Within the scope of the test, the collective-fixed static longitudinal stability of the OH-58A helicopter with the 250-C20 engine is essentially unchanged from the basic OH-58A helicopter.

Autorotational Characteristics

22. The response of the helicopter to simulated sudden engine failures was evaluated under the conditions shown in table 1. The aircraft was trimmed in balanced flight and with the controls fixed, the throttle was rapidly retarded to the flight-idle position (throttle chop). Recoveries were initiated at a minimum rotor speed of 304 rpm, a maximum pitch attitude of 30 degrees, or a maximum roll attitude of 45 degrees. Test results are presented in figures 15 and 16, appendix D. A true sudden engine failure could not be simulated by rapidly closing the throttle since the fuel control limited the engine deceleration. An engine torque decay time constant (time to 63 percent of initial value) of 1.1 second was measured for the 250-C20 engine, compared to a time constant of 0.6 second for the T63-A-700 engine. As a result of the larger engine torque decay time constant, the rate of rotor decay and aircraft reactions were not as great as those previously tested with the T63-A-700 engine (figs. 15 and 16). To determine the rate of rotor decay for a sudden engine failure, an analytical method was used with a time constant of zero. By assuming that the power coefficients (Cp's) before and after the throttle chop are equal, the following equation for rate of rotor decay can be derived:

$$\frac{d\Omega}{dt} = \frac{\frac{-I \Omega o^{2}}{Qo}}{t^{2} + \left(\frac{2I \Omega o}{Qo}\right)(t) + \left(\frac{I \Omega o}{Qo}\right)^{2}}$$

Where:
$$\frac{d\Omega}{dt}$$
 = rate of rotor decay

I = main rotor inertia

t = time after engine failure

 Ω o = initial main rotor speed

Qo = initial main rotor torque

This equation was solved for $d\Omega/dt$ at the following:

$$t = 1 second$$

$$I = 607 \text{ slug/ft}^2$$

 Ω o = 354 rev/min

Qo = from 1881 ft-1b to 4703 ft-1b

The results of this analysis show that at 100-percent main rotor torque a main rotor decay rate of 50 rpm per second (rpm/sec) would be encountered, compared to a measured main rotor decay rate of 23 rpm/sec (figs. 15 and 16). This decay rate would not allow a 2-second delay before lowering the collective, as specified in paragraph 3.5.5 of MIL-II-8501A for a minimum transient rotor speed of 304 rpm. No attempt was made to calculate the magnitude of the aircraft reactions for a sudden engine failure; however, they would be greater than those measured.

23. The reaction of the helicopter following the throttle chop was a slight nose-up pitch during the first second followed by a substantial nose-down pitching motion. In addition, a left roll and left yaw were observed in all instances. The roll rate increased with increasing forward airspeed, while the yaw rate decreased as airspeed was increased. Control effectiveness during the recovery phase was adequate to avoid unsafe rates, attitudes, or airspeeds. The aircraft responses to sudden engine failure with the 250-C20 engine were similar to those previously observed with the basic OH-58A helicopter.

MISCELLANEOUS TESTS

Engine Characteristics

24. Engine characteristics of the 250-C20 engine to include fuel flow and power available were determined from the engine manufacturer's specifications (ref. 6. app. A). A comparison of the power available for the 250-C20 and the T63-A-700 engine is presented in figure 17, appendix D. Engine fuel-flow data for the 250-C20 engine are presented in figure 18. Inlet and exhaust losses were determined from data previously obtained with the T63-A-700 engine (ref. 1, app. A).

Engine Governing Characteristics

25. Static and dynamic droop characteristics of the 250-C20 engine governor were evaluated under the conditions listed in table 1. Static tests were conducted by trimming the helicopter at 103-percent power turbine speed (N₂), and incrementally lowering and raising the collective. Dynamic characteristics were evaluated by rapidly moving the collective between maximum-power and minimum-power settings. Test results are presented in table 2 and figure B.


Table 2. Dynamic Droop Characteristics in Level Flight at 80 KCAS. 1

Test Condition	Steady-State Engine Torque (psi) ²	Steady-State Rotor Speed (rpm)	Transient Rotor Speed (rpm)
Trim to down collective	63 to 21	354 to 361	 367 (max)
Trim to up collective	21 to 64	361 to 353	 345 (min)

¹OH-58 helicopter with Allison 250-C20 engine.

26. Rotor speed during the engine governing systems tests did not exceed the output shaft speed limit. A 12-rpm underspeed occurred during full-up collective positioning, but was not considered a critical factor. Within the scope of this test, the engine governing characteristics of the 250-C20 engine are satisfactory for Army use.

²Pounds per square inch.



CONCLUSIONS

GENERAL

- 27. The following conclusions were reached upon completion of testing.
- a. Within the scope of this test, the performance of the OH-58A helicopter with the Allison 250-C20 engine was improved over the basic OH-58A helicopter, while handling qualities were essentially unchanged (para 8).
- b. The out-of-ground-effect hover ceiling at a 3000-pound gross weight was increased to 10,000 feet from 4600 feet (para 11).
- c. The long-range cruise airspeed was increased to 111 knots calibrated airspeed from 104 knots calibrated airspeed (para 12).
- d. The increased engine power did not significantly increase the service ceiling over the basic OH-58A at identical gross weights (para 14).
 - e. One shortcoming was noted.

SHORTCOMING AFFECTING MISSION ACCOMPLISHMENT

28. Insufficient left directional control at 35 KTAS in right sideward flight is a shortcoming, correction of which is desirable (para 17).

SPECIFICATION COMPLIANCE

- 29. Within the scope of this test, the OH-58A helicopter with the 250-C20 engine failed to meet paragraph 3.3.4 of military specification MIL-H-8501A, in that insufficient left directional control was available during 35-KTAS right sideward flight (para 17).
- 30. A sudden engine failure at maximum torque would not meet paragraph 3.5.5 of military specification MIL-H-8501A, in that collective delay would be less than 1 second (para 22).

RECOMMENDATIONS

- 31. The shortcoming, correction of which is desirable, should be corrected as soon as possible.
- 32. The test results should be incorporated in the operator's manual if the OH-58A helicopter with the 250-C20 engine is released for operational use.

APPENDIX A. REFERENCES

- 1. Final Report, USAASTA, Project No. 68-30, Airworthiness and Flight Characteristics Test, Production OH-58A Helicopter, Unamed and Armed with XM27E1 Weapon System, Performance, September 1970.
- 2. Final Report, USAASTA, Project No. 68-30, Airworthiness and Flight Characteristics Test, Production OH-58A Helicopter, Unarmed and Armed with XM27E1 Weapon System, Stability and Control, October 1970.
- 3. Letter, AVSCOM, AMSAV-R-F, subject: Evaluation of Allison 250-C20 Engine in OH-58 Helicopter, Project No. 71-24, 24 June 1971.
- 4. Letter, AVSCOM, AMSAV-EF, subject: Evaluation of Allison 250-C20 Engine in OII-58 Helicopter (revision of letter dated 24 June 1971), Project No. 71-24, 6 August 1971.
- 5. Technical Manual, TM 55-1520-228-10, Operator's Manual, Army Model OII-58A Helicopter, 13 October 1970.
- 6. Model Specification, Detroit Diesel Allison Division of General Motors Corporation, No. C800-C, Commercial Turboshaft Engine, Model 250-C20, 1 September 1971.
- 7. Military Specification, MIL-H-8501A, Helicopter Flying and Ground Handling Qualities; General Requirements For, September 1961, with Amendment 1, 3 April 1962.

APPENDIX B. SAFETY-OF-FIGHT RELEASE



DEPARTMENT OF THE ARMY US ARMY AVIATION SYSTEMS COMMAND PO BOX 209, ST. LOUIS, MO 63166

AMSAV-EF

12 40 10

SUBJECT: Safety of Flight Release for USAAVSCOM/USAASTA

Project No. 71-24

Commanding Officer
U.S. Army Aviation
Systems Test Activity
ATTN: SAVTE-P

- 1. This letter constitutes a safety of flight release, in accordance with AMCR 70-33, for USAASTA to conduct USAAVSCOM/USAASTA Project No. 71-24, Evaluation of the Allison 250-C20 Engine in the OH-58A Helicopter.
- 2. The flight envelope and operating limitations for conduct of Project No. 71-24 shall be in accordance with the TM55-1520-228-10, OH-58A Operators Manual, except as noted below:
 - a. Instrument Markings
 - (1) Engine Oil Pressure Module

Double green arc	115 - 130 psig
Single green arc	90 - 115 psig
Yellow arc	50 - 90 psig
Red line at	50 psig

(2) Torquemeter

Red line at 74 3 psig - max
Yellow arc 63.0 - 74.3 psig - 5 min. oper
Green arc 0 - 63.0 psig - continuous oper

(3) Gas Produce Tach

Green arc 60% - 104% Red line at $104\% - \max$

NOTE:

Transient Limit 105% (max of 15 sec)

12 AUG W.

AMSAV-EF

SUBJECT: Safety of Flight Release for USAAVSCOM/USAASTA Project No. 71-24

(4) Turbine Outlet Temperature

Red line at 793°C - max (30 min. limit below 40°C O.A.T. and 5 min. limit above

40°C O.A.T.)

Yellow arc 737°C - 793°C - starting and transient

Green arc 330°C - 737°C continuous oper.

NOTE:

Transient limit 793°C to 843°C during power transients (6 sec. max)

Maximum for starting 793°C to 927°C (10 sec. max)

- b. Center of Gravity Limitations The maximum center of gravity limitations are shown in figure 1 (Incl 1).
 - c. Weight Limitations 3200 pounds maximum gross weight.
- d. Vertical Load Factor at the c.g. The maximum load factor versus gross weight is shown in figure 2 (Incl 2).
- e. Airframe and engine torque and output shaft (N2) speed limits are shown in figure 3 (Incl 3).
- f. Fatigue lives are the same as the standard OH-58A except for the pylon support link which has a 4800 hour retirement life for the test configuration.
- g. Ambient operating temperatures shall be limited to $100\,^{\circ}\mathrm{F}$ due to engine compartment cooling.
 - h. Special Instructions
- (1) Engine starting procedure shall be the same as that for the standard OH-58A.
- (2) During low power descents N_2 speeds up to 106% are authorized; as are transient N_2 speeds down to 98% upon power application for the purpose of evaluating engine governing characteristics.

1 2 AUG 1971

AMSAV-EF

SUBJECT: Safety of Flight Release for USAAVSCOM/USAASTA Project No. 71-24

- 3. This safety of flight release applies to the OH-58A/C2O resulting from the incorporation of the BHC retro-fit kit (P/N 206HA-108-1) and the Allison C2O engine in accordance with the retro-fit kit instructions.
- 4. Aircraft Logbook Entry:
- a. In accordance with the provisions of TM 38-750, the following entries will be made on the DA Form 2408-13 and will be perpetuated on each form during the period of the test, or until superseded by another safety of flight release, or until the reason for limitation is removed, or until the appropriate -10 and 10CL manuals are revised to reflect the limitations as normal procedure.
- (1) Block 17, "Test Aircraft Operate within limitations prescribed in the inclosed SOFR, (date)".
- (2) The above entry will be preceded by the entry of a circled red X within block 16, and block 7 adjusted when appropriate.
- b. An exact copy of this SOFR will be inserted into the aircraft logbook.

FOR THE COMMANDER:

3 Incl

as


ROBERT F. FORSYTH


LTC, TC


Actg Chief, Flt Std & Qual Div Directorate for RD&E

Copy furnished:
Commanding General
US Army Materiel Command
ATTN: AMCRD-FQ

AMCSF-A







APPENDIX C. TEST INSTRUMENTATION

The instrumentation installed for this test is listed below:

Pilot and Engineer Panel

Airspeed (boom system)
Altitude (boom system)
Free air temperature
Rotor speed
Engine torque pressure
Longitudinal control position
Lateral control position
Directional control position
Collective control position
Fuel-used indicator
Oscillograph correlation counter


Oscillograph


Throttle position
Rotor speed
Engine torque pressure
Collective control position
Directional control position
Yaw attitude
Yaw rate
Lateral control position
Roll attitude
Roll rate
Longitudinal control position
Pitch attitude
Pitch rate
Fingineer event


APPENDIX D. TEST DATA


INDEX


Figure								Figure Number
Hovering Performance		٠			٠			I and 2
Level Flight Performance								
Climb Performance	٠	٠	٠		٠			10
Sideward Hight Characteristics					٠			1.1
Trim Control Position Characteristics								
Static Longitudinal Stability								
Autorotational Entry Characteristics.								
Ingine Performance								


















































DOCUMENT CONTROL DATA - R & D					
(Security classification of fitte, body of ebattact and indexing a 1. ORIGINATING ACTIVITY (Corporate author)	nnotation must be eniered when the overell report is classified)				
Constitution activity (corporate action)					
US ARMY AVIATION SYSTEMS TEST ACTIV	VITY UNCLASSIFIED				
EDWARDS AIR FORCE BASE, CALIFORNIA					
3. REPORT TITLE					
EVALUATION OF THE OH-58A HELICOPTER	R WITH AN ALLISON 250-C20 ENGINE				
4 OESCRIPTIVE NOTES (Type of report and inclusive detec)					
FINAL REPORT 24 June 1971 5 AUTHOR(\$1 (First name, middle initial, last name)	through 7 January 1972				
EMMETT J. LAING, Project Officer/Engineer					
DONALD G. BROADHURST, MAJ, CE, US Ar	rmy Project Dilet				
	W. WERNER, SP5, US Army, Project Engineer				
6. REPORT DATE	78. TOTAL NO. OF PAGES 76. NO. OF REFS				
DECEMBER 1972	52 7				
SE. CONTRACT OR GRANT NO.	9a. ORIGINATOR'S REPORT NUMBER(S)				
	Va. var. pp.a.par. va.				
b. PROJECT NO.	USAASTA PROJECT NO. 71-24				
AVSCOM PROJECT NO. 71-24					
с.	9b. OTHER REPORT NO(5) (Any other numbers that may be seeigned this report)				
d.	NA NA				
10. Distribution STATEMENT Distribution limited to Unit	ted States Government agencies only; test and				
evaluation, December 1972. Other requests for	this document must be referred to the Commander,				
	i, Attention: AMSAV-EF, Post Office Box 209,				
St. Louis, Missouri 63166.	12. SPONSORING MILITARY ACTIVITY				
	US ARMY AVIATION SYSTEMS COMMAND				
	ATTN: AMSAV-EF				
	PO BOX 209, ST. LOUIS, MISSOURI 63166				
	1 0 box 207, 31. LOUIS, MISSOURI 03100				

The United States Army Aviation Systems Test Activity conducted a limited performance and handling qualities evaluation of the Bell Helicopter Company model OH-58A helicopter with an Allison 250-C20 engine installed. The evaluation was conducted at Edwards Air Force Base, and Bishop, California, during the period 22 September 1971 to 7 January 1972. Twenty-five flights, 21.2 productive test hours, were required for the evaluation. Test results obtained with the Allison 250-C20 engine were compared with those previously obtained with the standard T63-A-700 engine. The primary performance improvement noted was an increase in out-of-ground-effect hover ceiling at a 3000-pound gross weight to 10,000 feet from 4600 feet. The long-range cruise airspeed was increased to 111 knots true airspeed from 104 knots true airspeed at a 5000-foot density altitude and a 3000-pound gross weight. The increased engine power did not significantly increase the service ceiling over the basic OH-58A at identical gross weights. One shortcoming, insufficient left directional control at 35 knots true airspeed in right sideward flight, was noted. Within the scope of the test, the performance of the OH-58A helicopter with the Allison 250-C20 engine was improved over the basic OH-58A helicopter. Handling qualities were essentially unchanged.

UNCLASSIFIED

Security	Classi	fication
----------	--------	----------

Security Classification 14 KEY WORDS	LINKA			LINK B		LINKC	
	ROLE	wT	ROLE	WT	ROLE	₩T	
Limited performance and handling qualities evaluation Bell Helicopter Company model OH-58A helicopter Allison 250-C20 engine Increase in out-of-ground-effect hover ceiling Long-range cruise airspeed increased Insufficient left directional control Performance was improved							

UNCLASSIFIED

Security Classification